
## **Fiber- optics replacement** FOR YOUR PANELVIEW 550







M20A09-MB550FOL


- After the power supply and all cables have been disconnected, and the unit has cooled, remove rear plastic bezel.
- 2. Remove fiber optic and lamp.
- 3. Remove back cover.
- Disconnect ribbon cables. The touchscreen version has 3 cables, and the keypad version has two.







5. Disconnect lamp power cable extension (J4).



 Remove computer board (6 or 7 screws).



7. Remove the 4 screws that separate the LCD panel from the face.





M20A09-MB550FOL


8. Take the old fiber optics out and slider the new one in.



9. Re-attach the LCD panel with 4 screws previously removed.



**10.** Re-attach computer board with screws, and reconnect the 2 ribbon cables.





**11.** Plug your backlight or lamp back into J4.



**12.** Attach Back cover back on with screws and put you backlight or lamp back in place, put your new fiber optics back in place.



**13.** Test the Fiber Optics by powering up the unit, check if the screen shows a better display, if yes put on the backlight cover. Then mount it back into your machine.

Enjoy your rejuvenated Panelview 550! Call us to order more replacement parts.

## Keep your Panelview 550 up and running!



LED backlight MB550E





Fiber optic MB550FOS Fiber optic MB55FOL



Touchscreen MF550T



Keypad MF550K



Keypad-touchscreen MF550B

For Technical Support, Call **Take2 Electronics 1-877-260-3426** <u>Support@Monitech.com</u>



20 Howard Place Kitchener, Ontario N2K 4Z4 CANADA 519.725.222 www.monitech.com