LCD upgrade kit

FOR YOUR MODICON- PANELMATE (91-00918-03, 91-01064-00 & 91-00744-10)





IMPORTANT:

WARRANTY

Before using any MONITECH product please carefully review this Manual as well as any additional documentation provided with your shipment.

Attempting any of the following will void product warranty:

- unauthorized repairs or parts replacement
- inappropriate use or placement: exposing product to liquids, harmful gases, electrical shock, physical shock, temperatures beyond the range of -4°F to 140°F (-20°C to 60°C)
- use of electrical voltage other than 12V 4.16A (power supply and AC cable provided)
- Removal or modification of serial, product, or warranty labels.



WARNING

ELECTRICAL HAZARD
DO NOT OPEN



TO AVOID ELECTRICAL SHOCK DO NOT OPEN PRODUCT CASING. UNAUTHORIZED REPAIRS OR PARTS REPLACEMENT ARE PROHIBITED AND WILL VOID PRODUCT WARRANTY. PLEASE RETURN TO MONITECH FOR REPAIRS.

REMOVALE:


Step #1) Turn off turn off main power, turn off machine.

Step #2) Take out the monitor & controller from your machine by loosening all surrounding bolts. Power off your controller and monitor via switch. Unplug monitor and controller from machine.









Step #3) Make sure to take a picture of all your connections before unplugging any of your connections. Unplug your video cable and keypad cable.





Step #4) Take off controller.






Step #5) Take off your CRT from your machine.






Step #6) Take off all bolts surrounding front frame. Then lift front frame up and take out standoffs from front bezel.



INSTALLATION:


Step #7) Put front frame back on to the front bezel. Open the monitor that Monitech has supplied you. Place our monitor into opening shown the holes of the brackets should match. Use 4 bolts previously taken off the front frame to mount our monitor to the front frame.



Step #8) Put back the controller into the front bezel. Open our MK105 use our Hardware kit (MH2000) to fasten the controller to the front frame with bolts and screws.



Step #9) Takeout MAV066A from MK105 box. Do not use any of the other cables, those cables are only for testing the monitor on a computer. Plug-in MAV066A to your controller as shown and plug-in VGA cable to Monitech monitor and plug-in power jack into Monitech monitor.



Step #10) Plug your keypad connector back in. Plug monitor and controller back in. Turn on your control to test if monitor is working before mounting.



Step #11) If everything is alright. Turn off power to control then put front bezel with control and Monitech monitor back onto machine then turn on main power of your machine and turn on machine CNC machine and you're ready to go. If you need to adjust your screen size use our user guide.





Enjoy your rejuvenated Monitor. Call us to order more HMI replacement parts.	
M20A02-0800TMATE/0800T0744	Q

Keep your PANELMATE HMI's up and running!





ML121LLMATE -12.1" LCD
Upgrade for (Panelmate/Cutler)
with 14" CRT. Just take a picture
of your video connector

ML080MATE -8" LCD Upgrade for (Panelmate/Cutler) with 9" CRT. Just take a picture of your video connector





MPC21P -LCD Panel kit for the PanelMate 1775K MF1775T- Touchscreen and overlay and Plexiglas for Panelmate 1775T.

8.0" Tocushcreen.

For Technical Support, Call **1-877-493-6105**

Support@Monitech.com



20 Howard Place Kitchener, Ontario N2K 4Z4 CANADA 519.725.2222 www.monitech.com

Keep your AB PanelView's up and running!



Replacement: LCO's, Backlight's, Keypad's & Touchscreen's for the whole 550 line.



Replacement: LCO's, Backlight's, Keypad's & Touchscreen's for the whole 600 line.



Replacement: LCD's, Backlight's, Keypad's & Touchscreen's for the whole 900 line.



Replacement: LCD's, Backlight's, Keypad's & Touchscreen's for the whole 1000 line.



Replacement: CRT TO LCD CONVERTION's, Backlight's, Keypad's & Touchscreen's for the whole 1200 line.



Replacement: CRT TO LCD CONVERTION's, Backlight's, Keypad's & Touchscreen's for the whole 1400 line.