

- 1. CONNECT MAV 515 TO MAB405 (VIDEO OUT)
- 2. CONNECT THE OTHER END OF MAV515 TO THE MONITOR VGA
- 3. CONNECT POWER JACK FROM MAB405 TO THE MONITOR
- 4. CONNECT MAV 117(D-CONNECTOR) TO MAB405 (VIDEO IN)
- 5. CONNECT THE OTHER END (10 PIN CONNECTOR) OF MAV 117 TO YOUR CONTROLLER.
- 6. CONNECT THE POWER SOCKET FROM MAB405 TO POWER JACK FROM MAV117

For Technical Support, Call 1-877-493-6105 Support@Monitech.com

